



City of Rocklin Building Division

3970 Rocklin Road Rocklin CA 95677 (916) 625-5120 (Fax) 625-5195

REINSPECTION POLICY

A reinspection fee may be assessed on each inspection when work is not complete or when corrections called for are not made. (Community Development Fee Schedule/Resolution No. 2011-9)

1. A reinspection fee will be assessed on projects that are not ready for inspection. "Not Ready" means that the work was not sufficiently complete to accomplish the requested inspections. Also, a reinspection fee will be assessed when items listed on a "Notice of Corrections" have not been completed.
2. Should the building inspector determine that a reinspection fee is appropriate, a "Reinspection Fee" slip will be left at your job site. No further building inspections will occur until the fee has been paid.
3. Reinspection fee payments need to be made at the City of Rocklin Building Division office at 3970 Rocklin Road, first floor. A reinspection fee of \$163.00 will be assessed. Please make your check in the amount of \$163.00 payable to the City of Rocklin. If you are paying cash, please have exact change.
4. An inspection can be scheduled providing that the reinspection fee is paid by 8:00 am on the morning of the scheduled inspection.
5. A canceled inspection will be accepted (if canceled by 8:00 am) the morning of the inspection.

Please contact the Building Division at 625-5120 should you have any questions or concerns regarding this policy.